

Temperaturkontrolle Tiefkühl-/Kühlager

Bereich: Restaurant

Monat/Jahr: 12/2019

Tag	Raum/Ort Kühlschrank Küche 1	Raum/Ort Kühlschrank Küche 2	Raum/Ort Kühlraum	Raum/Ort TK-Schrank	Raum/Ort TK-Truhe	Unterschrift
1	+6 °C	+3 °C	+4 °C	-19 °C	-21 °C	A. Koch
2						
3	+6 °C	+4 °C	+2 °C	-19 °C	-21 °C	A. Koch
4	+7 °C	+3 °C	+2 °C	-19 °C	-21 °C	A. Koch
5	+6 °C	+4 °C	+3 °C	-19 °C	-21 °C	A. Koch
6	+7 °C	+2 °C	+3 °C	-19 °C	-21 °C	A. Koch
7	+5 °C	+3 °C	+4 °C	-19 °C	-21 °C	A. Koch
8	+6 °C	+3 °C	+3 °C	-19 °C	-21 °C	A. Koch
9						
10	+6 °C	+2 °C	+3 °C	-19 °C	-21 °C	A. Koch
11	+6 °C	+3 °C	+12 °C	-19 °C	-21 °C	A. Koch
12	+7 °C	+4 °C	+2 °C	-19 °C	-21 °C	A. Koch
13	+7 °C	+3 °C	+3 °C	-19 °C	-21 °C	A. Koch
14	+6 °C	+3 °C	+2 °C	-19 °C	-21 °C	A. Koch
15	+6 °C	+4 °C	+3 °C	-19 °C	-21 °C	A. Koch
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
Bemerkungen/Abweichungen						
11.12.2019: Notdienst verständigt; Aggregat repariert						

Ablage: Ordner Kühltemperaturen